


US of SD of New York  
Appeal Clerk  
for Bankruptcy

July 16  
2012



RE: <sup>aka</sup> GM  
Motors liquidation  
etal

MARJORIE A. CREAMER

- for filing purposes
- Exhibit A + B
- Pre Argument Statement PART A + B
- Mo. for time
- IFP + Motion
- Financial Affidavit

Thank you  
Marjorie A. Creamer

Clery Mailer

for #09-50026  
Appeal of SD of NY

- Exhibit A + B
- Pro Argument Statement PART A + B
- Mo. for time
- JFP + Matw
- Financial Affidavit

Thank you  
Nephe A. Cramer  
July 17, 2012

Clerk of Court  
U.S. Dist  
Appeal of SD of NY  
1 Bowling Green  
NY NY 10004

Dickstein/Slovis  
1633 Broadway  
NY NY 10019-6708



573

# GM recalling over 400,000 Chevy Cruze

By Peter Valdes-Dapena @PeterDrives June 22, 2012 2:20 PM ET



GM will modify an engine shield that could create a fire hazard

NEW YORK (CNNMoney) -- General Motors is recalling 413,418 Chevrolet Cruze small cars that could create a fire hazard.

The engine shield, a large plastic piece that is installed under the front of the car to protect the engine, could trap oil that is accidentally spilled or dripped during oil changes.

Also, in cars with manual transmissions, driving with a worn clutch can cause burning hydraulic fluid to squirt from the clutch housing. The flaming fluid can ignite the engine shield leading to an engine compartment fire.

In a separate action involving some of the same cars, GM dealers will also inspect welds in the rear compartment to ensure they were properly applied. As many of the 249 of the cars may have incomplete welds.

The recalls involve all Cruzes built in the United States from September 2010, when the car first went into production in the U.S., through May, 2012.

### Cooler cars under \$18,000

The recalls follow a preliminary investigation by the National Highway Traffic Safety Administration into two engine compartment fires in 2011 Chevrolet Cruzes.

There are no known crashes, injuries or fatalities related to either recall, GM said in a press release Friday.

GM (GM, Fortune 500) dealers will modify the engine shield by cutting away parts of it, creating holes that will allow fluids to drip through. The modification process that will take about 30 minutes. Owners should make an appointment with their dealers "at their earliest convenience," GM said in a statement.

Weld repairs, if necessary, will take about three hours, GM said.

Notification letters will be mailed to owners beginning July 11.

The Cruze compact car was GM's replacement for the Chevrolet Cobalt. It was the company's best-selling car model last year.

th  
ca  
li

EXHIBIT  
A

Handwritten notes and stamps, including "EXHIBIT A" and various illegible markings.



<

Posted: Sat 2:28 AM, Jun 23, 2012

[Back to News](#)

## GM Recalling Over 400,000 Chevy Cruzes

General Motors is recalling 413,418 Chevrolet Cruze small cars to modify an engine shield that could create a fire hazard.

The engine shield, a large plastic piece that is installed under the front of the car to protect the engine, could trap oil that is accidentally spilled or dripped during oil changes.

Also, in cars with manual transmissions, driving with a worn clutch can cause burning hydraulic fluid to squirt from the clutch housing. The flaming fluid can ignite the engine shield leading to an engine compartment fire.

In a separate action involving some of the same cars, GM dealers will also inspect welds in the rear compartment to ensure they were properly applied. As many of the 249 of the cars may have incomplete welds.

The recalls involve all Cruzes built in the United States from September 2010, when the car first went into production in the U.S., through May, 2012.

The recalls follow a preliminary investigation by the National Highway Traffic Safety Administration into two engine compartment fires in 2011 Chevrolet Cruzes.

There are no known crashes, injuries or fatalities related to either recall, GM said in a press release Friday.

GM (GM, Fortune 500) dealers will modify the engine shield by cutting away parts of it, creating holes that will allow fluids to drip through. The modification process that will take about 30 minutes. Owners should make an appointment with their dealers "at their earliest convenience," GM said in a statement.

Weld repairs, if necessary, will take about three hours, GM said.

Notification letters will be mailed to owners beginning July 11.

The Cruze compact car was GM's replacement for the Chevrolet Cobalt. It was the company's best-selling car model last year.

*Copyright 2012 by The Associated Press. All Rights Reserved.*



EXHIBIT B

[Next Story >](#)

**Find this article at:**

[http://www.witn.com/news/headlines/GM\\_Recalling\\_Over\\_400000\\_Chevy\\_Cruzes\\_160102495.html?ref=495](http://www.witn.com/news/headlines/GM_Recalling_Over_400000_Chevy_Cruzes_160102495.html?ref=495)

Check the box to include the list of links referenced in the article.

Copyright © 2002-2010 - Gray Television Group, Inc.