


**UNITED STATES BANKRUPTCY COURT
SOUTHERN DISTRICT OF NEW YORK**



WITHDRAWAL OF CLAIM

Debtor Name and Case Number:	<input checked="" type="checkbox"/> Motors Liquidation Company, Case No. 09-50026 <input type="checkbox"/> MLC of Harlem, Inc., Case No. 09-13558 <input type="checkbox"/> MLCS, LLC, Case No. 09-50027 <input type="checkbox"/> MLCS Distribution Corporation, Case No. 09-50028 <input type="checkbox"/> Remediation and Liability Management Company, Inc., Case No. 09-50029 <input type="checkbox"/> Environmental Corporate Remediation Company, Inc., Case No. 09-50030
Creditor Name and Address:	KELLY TRIDLE 29 HILLCREST COURT OGALLALA, NE 69153
Claim Number (if known):	64964
Date Claim Filed:	11/30/2009
Total Amount of Claim Filed:	\$4,800.00 \$2360.76

I, the undersigned, am the above-referenced creditor, or an authorized signatory for the above-referenced creditor. I hereby withdraw the above-referenced claim and authorize the Clerk of this Court, or their duly appointed Claims Agent, to reflect this withdrawal on the official claims register for the above-referenced Debtor.

Dated: 06-04-10

Kelly Tridle

Print Name: Kelly Tridle

Title (if applicable): _____

VIA EMAIL AND FIRST CLASS MAIL

Motors Liquidation Company
Attn: Claims Team
2101 Cedar Springs Road
Suite 1100
Dallas, TX 75201
claims@motorsliquidation.com

RECEIVED
JUN 10 2010

**Re: In re Motors Liquidation Company, et al. ("Debtors"), Case No. 09-50026 (REG) –
Claim Documentation Letter**

Dear Motors Liquidation Company,

By this letter, I hereby submit the attached documentation in support of the following claim:

Claim Number	Claimant
64964	KELLY TRIDLE

I understand and acknowledge that submission of this letter does not constitute allowance of the above-described claim, and that the Debtors reserve all rights with respect to this claim.

Very truly yours,

X

Print Name

Address

City, State and Zip Code

Kelly Tridle
Kelly Tridle
29 Hillcrest Court
Osallala, NE 69153

Osallala, NE 69153

GENERAL MOTORS PRODUCT PROGRAM CUSTOMER REIMBURSEMENT CLAIM FORM**THIS SECTION TO BE COMPLETED BY CLAIMANT**

Date Claim Submitted: 06-04-10 - This Claim

11-27-09 - 2nd claim

app. - 11-01-07 - First claim

Vehicle Identification Number (VIN): 1G2WP12K02F250448

Mileage at Time of Repair: 69,712

Date of Repair: 8/6/2007

Claimant Name (please print): Kelly F. TRIOLE

Street Address or PO Box Number: 29 HillCrest Court

City, State, ZIP Code: OGallala, NE. 69153

Daytime Telephone Number (include Area Code): 308-289-4824

Evening Telephone Number (include Area Code): 308-289-4824

308-539-1735

Amount of Reimbursement Requested: \$ 2360.76

Zoom

Sized for Print

Automotive Service Solutions, LLC

2808 Spruce
Acres
Ogallala, NE

Repair Order

Phone # 308.284.4465

Business Hours:

Fax # 308.284.4486

M-F 7:30 - 5:30

http://www.automotivesllc.com

Date	RO #	Written By:
8/6/2007	70575	PEP
Terms	Due on receipt	

Kelly Tridle
398 Road East R
Paxton, Nebr. 69155

308-289-4824-Cell

Fleet #	
Year	2002
Model	Grand Prix GT
Odometer In:	69,712
Odometer Out:	

Make	Pontiac
VIN	1G2WP12K02F250448
License #	68-G998

Tech	Description	Quantity	Total
	Work Requested-Customer states that the vehicle will not start & indicated there is something at the top of the engine that has a hole in it & requested that the vehicle be inspected for repair. Check accordingly & estimate please.		0.00T
	Work Performed-Verified the customers concern-NOTED the Engine Upper Intake Manifold (Plenum) Assembly to have a burn thru hole in it as well as melted Fuel Injector Harness Wiring, Engine Fueling Pressure & Return Lines are melted, the Engine Emissions Exhaust Recirculation Valve is sticking possibly due to heat, the Engine Fueling Electric Fuel Pump Assembly is not carrying any Pressure and the Engine Emissions Exhaust System Catalytic Converter is restricted. The Engine Upper Intake Manifold(Plenum) Assembly, Engine Fueling Pressure & Return Lines, Engine Emissions Exhaust Gas Recirculation Valve, Engine Fueling Electric Fuel Pump Assembly, Engine Emissions Exhaust System Catalytic Converter Assembly all require replacement for proper repair as well as the Engine Fueling Injector Wiring Harness needs to be repaired. Estimated the repair & per Phone conversation between Kelly & Pam the repair was authorized. Replaced the Engine Upper Intake Manifold (Plenum) Assembly, Both the Engine Fueling Pressure & Return Lines, the Engine Fueling Electric Fuel Pump Assembly, Engine Emissions Exhaust Gas Recirculation Valve, Engine Emissions Exhaust System Catalytic Converter Assembly & Repaired the Burnt Engine Fueling Injector Wiring Harness Assembly. Verified the repair-the Vehicle is at this time performing as design intended.		0.00
	Labor	9	513.00
	Engine Upper Intake Manifold (Plenum) Assembly # 89017272	1	158.00T
	Engine Upper Intake Manifold Gasket (Plenum) Assembly # 89017554	1	37.00T
	Engine Positive Crankcase Ventilation Valve Assembly # 89017274	1	23.47T
	Engine Fueling Throttle Body Gasket Assembly # G 31594	1	6.80T
	Engine Fueling System Pressure Pipe Assembly # 15279855	1	87.02T
	Engine Fueling System Return Pipe Assembly # 15279854	1	89.70T
	Engine Fueling Electric Fuel Pump Module Assembly # 1917221	1	570.74T
	Engine Fueling Fuel Filter Assembly # 86311	1	24.52T
	Engine Emissions Exhaust Gas Recirculation Valve Assembly # EGV589	1	239.85T
	Engine Exhaust System Catalytic Converter Assembly # 642583	1	433.85T
	Shipping & Handling		45.93T
	Shop supplies		5.00T

We appreciate your business!

The only warranties applying to this part(s) are those which may be offered by the manufacturer. The Seller hereby expressly disclaims all warranties, either express or implied, including any implied warranties of merchantability or fitness for a particular purpose, and neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this part(s) and/or service. Buyer shall not be entitled to recover from the Seller any consequential damages, damages to property, damages for loss of use, loss of time, loss of profits, or income, or any other incidental damages.

Total
Amount Paid:
Paid by: Cash ___ CC ___ Ck# _____

Signature _____ Date _____

Federal, state and local environmental regulations regarding the use of chemicals and generation of wastes (solvents, oils, caustics, lead, asbestos, etc.) and how they are stored, managed and disposed of, has resulted in an increase in cost of service. Ordinarily, increased costs simply result in an increased hourly labor charge. We at Automotive Service Solutions, LLC, have decided in lieu of raising our labor rate, to list a compliance charge on appropriate service bills.

Automotive Service Solutions will provide a courtesy loaner vehicle for virtually any service visit. In an effort to offset fuel and maintenance costs, a \$10.00 fee will be added to this invoice for each day the loaner is used, regardless of how long it may be used.

Automotive Service Solutions, LLC

2808 Spruce
Acres
Oaallala. NE

Repair Order

Phone # 308.284.4465

Business Hours:

Fax # 308.284.4486

M-F 7:30 - 5:30

http://www.automotivessllc.com

Date	RO #	Written By:
8/6/2007	70575	PEP
Terms	Due on receipt	

Kelly Tridle
398 Road East R
Paxton, Nebr. 69155

308-289-4824-Cell

Fleet #

Year

2002

Make

Pontiac

Model

Grand Prix GT

VIN

1G2WP12K02f250448

Odometer In:

69,712

License #

68-G998

Odometer Out:

Tech	Description	Quantity	Total
	Hazmat Sales Tax - State & City		5.00T 120.88
<i>We appreciate your business!</i>			

Paid Ch # 1400

The only warranties applying to this part(s) are those which may be offered by the manufacturer. The Seller hereby expressly disclaims all warranties, either express or implied, including any implied warranties of merchantability or fitness for a particular purpose, and neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this part(s) and/or service. Buyer shall not be entitled to recover from the Seller any consequential damages, damages to property, damages for loss of use, loss of time, loss of profits, or income, or any other incidental damages.

Total **\$2,360.76**

Amount Paid:

Paid by: Cash ___ CC ___ Ck# ___

Signature

Date

Federal, state and local environmental regulations regarding the use of chemicals and generation of wastes (solvents, oils, caustics, lead, asbestos, etc.) and how they are stored, managed and disposed of, has resulted in an increase in cost of service. Ordinarily, increased costs simply result in an increased hourly labor charge. We at Automotive Service Solutions, LLC, have decided in lieu of raising our labor rate, to list a compliance charge on appropriate service bills.

Automotive Service Solutions will provide a courtesy loaner vehicle for virtually any service visit. In an effort to offset fuel and maintenance costs, a \$10.00 fee will be added to this invoice for each day the loaner is used, regardless of how long it may be used.